PRINTED: 07/13/2015 FORM APPROVED

	or hearn service Ke	The state of the s			
	OF CORRECTION	(XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIS A. BUILDIN	PLE CONSTRUCTION 3: 01	(X3) DAYE SURVEY COMPLETED
		FCL035028	B. WING _	<u> </u>	R 07/10/2015
NAME OF I	PROVIDER OR SUPPLIER	STREET A	DRESS CITY	, STATE, ZIP CODE	
			PKIN BLVD	ALIO G. 2005	
PIONEE	R HEALTHCARE #1		IRG, NC 27	549	
(X4) ID	SUMMARY STA	TEMENT OF DEFICIENCIES	ID.	PROVIDER'S PLAN OF CORRECT	TION (XIS)
PRÉFIX TAG		YMUST BE PRECEDED BY FULL SCIDENTIFYING INFORMATION)	PREF-X TAG	(EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPR DEFICIENCY)	
(C 000)	Initial Comments		(C 000)	2. The closet do	
	Report by Suzanna	Fay		in bedroom 4 h	33 been
	DHSP Construction	Section conducted a Biennial		replaced.	
		n July 10, 2015 from 9:35 AM		3. The Electrical	. so a-
		above referenced facility. Not			
		cited deficiencies were		in the halfbata	nism
	corrected. Therefo	re, further action is required.			0.0
	The remaining defic	ciencies are as follows:		has been repaired	c ame
				replaced again	
(C 174)	Building Equipment	Maintained Safe, Operating	{C 174}	1 - "	120
	SECTION .0300 - 1	THE BUILDING .		4. The extensor sof	121 acr
		117 BUILDING SERVICE		10 1	heen-
	EQUIPMENT		1	Hasa true no	
		nd all fire safety, electrical,	i	fosis tim has replaced at the	roper
		umbing equipment in a family maintained in a safe and		Top/La	
	operating condition.			portion.	
		apply to new and existing		1 2 400	C++0
	family care homes.		ì	The fight from	D. / - /
	This Rule is not me			the right Gron	t :
		vealed that the door hardware	ř	lace 1 duy	conker
		closet doors in Bedroom 4 ould not open the doors.		entrance with	Town !!
		rson repair the closet doors.		Dair bas be	E-M-
	Provide documenta	tion of the repairs.	į	pant has been support off and	1 reparted
	7/10/15: SF-Observ	rations revealed that one door		> delblass off	1
		and the right hand knob was		Dispesse see Pla	fure
		qualified person repair the	ţ	Library 200	
i		de documentation of the		Via your ensu	
	repairs through pho	IDS.		J	, , !
	3. Observations re-	vealed that the electrical outlet	į	- Routine query	techy
i		in the hall bathroom did not		108 De other word	holder:
		ime of this survey. Have a		by exclosion that we to	detect problems
Shale len of the	qualified technician ealth Service Regulation	repair or replace the outlet.		on time and fix	Killmah dar
		ER/SUPPLIER REPRESENTATIVE'S SIG	NATURE	TITLE	according,
	Bris	eget Dunik	ri -B50	3 administra	to 8/5/15
STATE FORM	И	X	6893	K1HI22	If continuation sheet 1 of 2

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING 07/10/2015 FCL035028 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 306 LUMPKIN BLVD PIONEER HEALTHCARE #1 LOUISBURG, NC 27549 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE COMPLETE PREFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) (C 174) Continued From page 1 (C 174) Provide documentation of the repairs. 7/10/15: SF-At the time of this survey, the electrical outlet did not have power. Have a qualified technician repair the outlet. Provide documentation of the repairs through copies of receipts or work orders. Observations revealed that a section of the exterior soffit and fascia trim was rotted and heavily damaged to the left of the front entrance. Have a qualified person repair the soffit and trim Provide documentation of the repairs. SEE PAGE 7/10/15: SF-Observations revealed that the soffit had been partially repaired. There was still a section that showed rot along the fascia leaving an open gap between the soffit and the fascia trim. Have a qualified person complete the repairs to the soffit. Provide documentation of the repairs through photos or copies of receipts or work orders. Observations revealed that the paint was flaking at the soffit to the right of the front entrance. Have a qualified person repair the soffit. Provide documentation of the repairs. 7/10/15: SF-Observations revealed that the right side of the soffit had not been repaired. Have a qualified person repair the section of soffit where the paint is flaking and peeling. Provide documentation of the repairs through photos or copies of receipts or work orders.

K1HI22

MR. DONALD TAYLOR 1404 HAZELNUT DRIVE RALEIGH, NORTH CAROLINA 27610 (919)-832-0030 (HOME) (919) 501-5077 (PAGER)

INVOICE INVOICE NUMBER: INVOICE DATE: 7-17-15 ATTN:

CUSTOMER: PIONEER HERITACORe In C. Justice Street /306 Lumpkin Blvd

REMIT TO: 1404 HAZELNUT DRIVE RALEIGH, NORTH CAROLINA 27610

MAKE CHECK PAYABLE TO MR. DONALD TAYLOR.

DATE	DESCRIPTION OF SERVICES	AMOUNT
7-17.15	Bathroom Sink Clogged	
١.	Routed (Snaked from	
	Under the house.	
	(Crawl Space)	
/2	Installed one Ground fault GFC 1 Recepticher	\ \
	on Hall battroom	/
	LABOR AND MATERIALS WE APPRECIATE VOUR BUSINESS! TOTAL	195 00

I WE APPRECIATE VOUR BUSINESS!